Streetcar Update

Review of February 2018




Cincinnati Bell' connector

Safety Metrics: Near Miss


Near Miss Incident Breakdown

- 83% initiated by other vehicle:
 - Most interactions due to maneuvers in front of or around Streetcar (Cut's off, red light running)
 - 15% Pedestrian Interactions (Jay walking)
- Incidents most likely to occur: Main at 5th
- Most likely to occur:
 - Fridays
 - 11:00 and Noon, 4 pm and 5 pm



Safety Metrics: Reportable Incidents

- 6 Reportable Incidents in 2018: 3 Collisions, 1 collision/derailment, 1 derailment and 1 evacuation
- No reportable incidents in February



Safety and Security Activities

- 2/12/18 2/14/18 ODOT Quarterly
- Weekly SSRC and CAP committee meetings
- Confirmation of 27 closed CAP's with an additional 9 pending
- 2/16/18 ODOT adopts and approves revised Accident Investigation SOP

Marketing/Communications

Partnered with Over-the-Rhine Chamber to produce updated street maps and tear-off maps for distribution through retail and restaurants



Marketing/Communications

Facebook

Followers: **4,028 by 3**

Reach: **17,152**

Engagements: 820



Twitter

Followers: **4,368 b**y 44

Impressions: 136K

Engagements: 433

<u>Instagram</u>

Followers: **1,014 by** 11

Engagements: 209

February Ridership Summary


	Ridership	Ridership Budget	Variance		
Weekday	12,648	17,705	-5,057		
Saturday	6,130	11,549	-5,419		
Sunday	3,650	5,838	-2,188 -		
Holiday	-	-			
Total	22,428	35,092	-12,664		

Note: no service Wednesday 2/7 and Thursday 2/8 due to ice on overhead contact system


^{*}Includes any supplemental service

^{*}Does not include charter service

Fare Inspections




Citations



Fare Compliance


Fare Evasion Rate



February Operations Summary


	Trips heduled	Trips Operated	Missed Trips*	Average Headway	Blockages	Signal Failures	Close Calls	TAA	Charter
2	2,100	1,852	248	12:55 (12 min) 15:15 (15 min)	125 (total) 94 (more than 2 min)	2 (total) 2 (more than 2 min)	13	20	0

Operations Trends




Operations Trends

Change Off Road




Streetcar vehicle failure resulting in removal of vehicle from service; can be a failure of a safety device or electro/mechanical failure – requires offload of passengers and results in 60+ minutes suspension of service and can result in reduced service (increased headway)

Train Failure Road



Streetcar vehicle failure that can be remedied on the line – typically results in 5 to 60 minutes suspension of service

Operations Trends



Ticket Vending Machines

- Waterproofing and Installation/Electrical
 - 19 TVMs
 - Upgrades complete on schedule on budget
 - Extended Warranty
- Hardwire Banks Station
 - Elimination cellular connection
 - Improved reliability



Vehicle Status

- Overall fleet minor crash damage repair
- 1177 out of service crash damage
 - 1/19 major incident with automobile
 - Derailment inspection
 - Long lead parts
- 1179 out of service
 - Wheel issues

QUESTIONS?